

**Enclosed is the December 2018 SIR INCAL DVD-ROM.**

Please take a moment to review the information in this cover letter for details regarding the contents of the SIR INCAL DVD-ROM.

**What is Service Information Regulation (SIR)?**

Beginning with the EPA 2013 engine launches, the Service Information Regulation (SIR) requires that Cummins Inc. provide the applicable INSITE calibrations to interested parties not affiliated with the Cummins Authorized service channel.

**What is INCAL?**

The INCAL DVD contains all the MidRange and Heavy-Duty calibrations for EPA 2013 and beyond automotive applications. For the INCAL DVDs details, please see the listings below.

**Changes in Calibrations**

INSITE Pro version 8.1.4 or later will be needed to access calibrations on this INCAL DVD and calibrations that were saved from QSOL or INSITE’s ECM/PDD Code Search after July 25, 2016. This free update will be pushed to all licensed users of INSITE Pro. Older versions of INSITE Pro will not recognize calibrations on this INCAL DVD or those saved after July 25, 2016. INSITE functionality and the process to retrieve and install calibrations has not changed.

**December 2018 SIR INCAL DVD-ROM Content:**

B6.7 CM2350 B121B/B141B	Aftertreatment Diesel Exhaust Fluid Controller
ISB - CM2150	Aftertreatment Diesel Exhaust Fluid Dosing Unit
ISB6.7 CM2250	Electric Fuel Lift Pump
ISB6.7 CM2350 B101	Engine Fuel Supply Pump
ISB6.7 G CM2180/CM2380 B118	Turbo Actuator Controller
ISC - CM2150	
ISC8.3 CM2250	
ISL - CM2150D	
ISL9 CM2250	
ISL9 CM2350 L101/L108/L109/L123B	
ISL G - CM2180/CM2380	
ISM - CM876	
ISX - CM871	
ISX12/11.9/15 CM2250	
ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109	
ISX12 G CM2180/CM2380 EJ	
ISV5 CM3230 V104	
L9 CM2350 L116B	
X15 CM2350 X114B/X116B	

**Have Comments?**

We would like to know how well this information meets your needs. Please call Cummins Electronic Support Products at 1-800-CUMMINS (select option 2 and then option 3) with your comments.