

PLEASE NOTE THE FOLLOWING IMPORTANT CHANGES:

All INCAL DVD-ROMs are available for download at <https://www.cummins.com/support/digital-products-and-services-support/incal-support#software-downloads>

Enclosed is the December 2021 SIR INCAL DVD-ROM.

Please take a moment to review the information in this cover letter for details regarding the contents of the SIR INCAL DVD-ROM.

What is Service Information Regulation (SIR)?

Beginning with the EPA 2013 engine launches, the Service Information Regulation (SIR) requires that Cummins Inc. provide the applicable INSITE calibrations to interested parties not affiliated with the Cummins Authorized service channel.

What is INCAL?

The INCAL DVD contains all the MidRange and Heavy-Duty calibrations for EPA 2013 and beyond automotive applications. For the INCAL DVDs details, please see the listings below.

Changes in Calibrations

New engine control module (ECM) calibration codes have been released using industry standard encryption for all electronically controlled engine products. These ECM calibration codes are only supported in Cummins INSITE™ electronic service tool version 8.7.0 and newer. If users do not upgrade, users will not be able to use any calibrations on these INCAL DVDs or downloaded through Quickserve Online (QSOL) or Cal over web. Any previous INCAL DVDs are still supported during the existing expiration dates.

December 2021 SIR INCAL DVD-ROM Content:

DVD 1

B6.7 CM2350 B121B/B141B
ISB6.7 G CM2180/CM2380 B118
ISV5 CM3230 V104
L9 CM2350 L116B
X15 CM2350 X114B/X116B

DVD 2

B6.7N CM2380 B150B
ISB - CM2150
ISB6.7 CM2250
ISB6.7 CM2350 B101
ISC - CM2150
ISC8.3 CM2250
ISL - CM2150D

ISL9 CM2250
ISL G - CM2180/CM2380
ISM - CM876
ISX - CM871
ISX12/11.9/15 CM2250
ISX12 G CM2180/CM2380 EJ
ISX12N CM2380 X120B
L9 CM2450 L126B/L127B
L9N CM2380 L124B/L130B
X12 CM2450 X137B
X15 CM2450 X124B/X134B

DVD 3

B6.7 CM2450 B155B	Aftertreatment Diesel Exhaust Fluid Controller
ISL9 CM2350 L101/L108/L109/L123B	Aftertreatment Diesel Exhaust Fluid Dosing Unit
ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109	Electric Fuel Lift Pump
	Engine Fuel Supply Pump
	Fuel Control Valve
	Ignition Control Module
	Throttle Actuator
	Turbo Actuator Controller

Have Comments?

We would like to know how well this information meets your needs. Please call Cummins Care at 1-800-CUMMINS (select option 2 and then option 3) with your comments.