

PLEASE NOTE THE FOLLOWING IMPORTANT CHANGES:

All INCAL DVD-ROMs are available for download at <https://www.cummins.com/support/digital-products-and-services-support/incal-support#software-downloads>

Enclosed is the September 2021 SIR INCAL DVD-ROM.

Please take a moment to review the information in this cover letter for details regarding the contents of the SIR INCAL DVD-ROM.

What is Service Information Regulation (SIR)?

Beginning with the EPA 2013 engine launches, the Service Information Regulation (SIR) requires that Cummins Inc. provide the applicable INSITE calibrations to interested parties not affiliated with the Cummins Authorized service channel.

What is INCAL?

The INCAL DVD contains all the MidRange and Heavy-Duty calibrations for EPA 2013 and beyond automotive applications. For the INCAL DVDs details, please see the listings below.

Changes in Calibrations

New engine control module (ECM) calibration codes have been released using industry standard encryption for all electronically controlled engine products. These ECM calibration codes are only supported in Cummins INSITE™ electronic service tool version 8.7.0 and newer. If users do not upgrade, users will not be able to use any calibrations on these INCAL DVDs or downloaded through Quickserve Online (QSOL) or Cal over web. Any previous INCAL DVDs are still supported during the existing expiration dates.

September 2021 SIR INCAL DVD-ROM Content:

DVD 1

B6.7 CM2350 B121B/B141B
ISB - CM2150
ISB6.7 CM2250
ISB6.7 G CM2180/CM2380 B118
ISC - CM2150
ISC8.3 CM2250
ISL9 CM2350 L101/L108/L109/L123B
ISV5 CM3230 V104
L9 CM2350 L116B
X15 CM2350 X114B/X116B

DVD 2

B6.7 CM2450 B155B	Aftertreatment Diesel Exhaust Fluid Controller
B6.7N CM2380 B150B	Aftertreatment Diesel Exhaust Fluid Dosing Unit

ISB6.7 CM2350 B101	Electric Fuel Lift Pump
ISL - CM2150D	Engine Fuel Supply Pump
ISL G - CM2180/CM2380	Fuel Control Valve
ISL9 CM2250	Ignition Control Module
ISL9.5 NS5 2880E IAT	Throttle Actuator
ISM - CM876	Turbo Actuator Controller
ISX - CM871	Turbocharger Compressor Bypass Control Valve
ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109	
ISX12 G CM2180/CM2380 EJ	
ISX12N CM2380 X120B	
ISX12/11.9/15 CM2250	
L9 CM2450 L126B/L127B	
L9N CM2380 L124B/L130B	
X12 CM2450 X137B	
X15 CM2450 X124B/X134B	

Have Comments?

We would like to know how well this information meets your needs. Please call Cummins Care at 1-800-CUMMINS (select option 2 and then option 3) with your comments.